


Hoodman LP21 Drone Landing Pad

Folding instructions



Hold Landing Pad vertical in front of you



Allow top half of Pad to fold down over the bottom half and hold as pictured



Bring wrists together



Place black rubber band over point of folded pad to hold in collapsed position



HOODMAN CORPORATION | (310) 222-8608 | WWW.HOODMANUSA.COM

Made in China